



Transport Accident
Investigation
Commission

Final Report

Tuhinga whakamutunga

Rail inquiry RO-2025-104
Wellington Station signalling power outage
Wellington
27 March 2025

June 2026



The Transport Accident Investigation Commission

Te Kōmihana Tirotiro Aituā Waka

No repeat accidents – ever!

“The principal purpose of the Commission shall be to determine the circumstances and causes of accidents and incidents with a view to avoiding similar occurrences in the future, rather than to ascribe blame to any person.”

Transport Accident Investigation Commission Act 1990, s4 Purpose

The Transport Accident Investigation Commission is an independent Crown entity and standing commission of inquiry. We investigate selected maritime, aviation and rail accidents and incidents that occur in New Zealand or involve New Zealand-registered aircraft or vessels.

Our investigations are for the purpose of avoiding similar accidents and incidents in the future. We determine and analyse contributing factors, explain circumstances and causes, identify safety issues, and make recommendations to improve safety. Our findings cannot be used to pursue criminal, civil, or regulatory action.

At the end of every inquiry, we share all relevant knowledge in a final report. We use our information and insight to influence others in the transport sector to improve safety, nationally and internationally.

Commissioners

Chief Commissioner	David Clarke
Deputy Chief Commissioner	Stephen Davies Howard
Commissioner	Paula Rose, QSO
Commissioner	Bernadette Roka Arapere (until 6 November 2025)

Key Commission personnel

Chief Executive	Martin Sawyers
Chief Investigator of Accidents	Louise Cook
Investigator-in-Charge for this inquiry	Barry Stephenson
Lead Investigator for this inquiry	Michael McKay
Commission General Counsel	Sid Wellik

Notes about Commission reports

Kōrero tāpiri ki ngā pūrongo o te Kōmihana

Photographs, diagrams, pictures

The Commission owns the photographs, diagrams and pictures in this report unless otherwise specified.

Verbal probability expressions

For clarity, the Commission uses standardised terminology where possible.

One example of this standardisation is the terminology used to describe the degree of probability (or likelihood) that an event happened, or a condition existed in support of a hypothesis. The Commission has adopted this terminology from the Intergovernmental Panel on Climate Change and Australian Transport Safety Bureau models. The Commission chose these models because of their simplicity, usability, and international use. The Commission considers these models reflect its functions. These functions include making findings and issuing recommendations based on a wide range of evidence, whether or not that evidence would be admissible in a court of law.

Terminology	Likelihood	Equivalent terms
Virtually certain	> 99% probability of occurrence	Almost certain
Very likely	> 90% probability	Highly likely, very probable
Likely	> 66% probability	Probable
About as likely as not	33% to 66% probability	More or less likely
Unlikely	< 33% probability	Improbable
Very unlikely	< 10% probability	Highly unlikely
Exceptionally unlikely	< 1% probability	



Figure 1: Location of incident

Contents

Rārangi take

1	Executive summary	4
	What happened	4
	Why it happened	4
	What we can learn	4
	Who may benefit	4
2	Factual information	6
	Background	6
	Narrative	9
	First occurrence	9
	Second occurrence	10
	Power supply module	10
	Personnel information	11
	Previous occurrence	11
	Organisational information	12
3	Analysis	13
	Introduction	13
	Why did the power supply module fail?	13
	Design assurance process for safety-critical systems	14
	Effectiveness of the alarm system	16
	Considerations for effective alarm system design	17
	The RealFlex alarm design	17
4	Findings	20
5	Safety issues and remedial action	21
	General	21
6	Recommendations	22
	General	22
7	Other safety lessons	23
8	Data summary	24
9	Conduct of the inquiry	25
	Abbreviations	26
	Glossary	27
	Citations	28

Figures

Figure 1: Location of incident.....	1
Figure 2: Westinghouse Brake and Signal Company power lever frame located in A-Box	6
Figure 3: Wellington Junction train control desk	7
Figure 4: Train control mimic screen	8
Figure 5: Wellington Junction train control mimic screen with alarm displaying	9
Figure 6: Wellington Station signalling schematic	11
Figure 7: Alarm presentation.....	18

1 Executive summary

Tuhinga whakarāpopoto

What happened

- 1.1. In March and May 2025, Wellington Station's signalling system, which had been replaced a few months earlier, suffered two significant outages caused by the failure of the same power supply module.
- 1.2. Each failure resulted in all signals within the station reverting to 'stop' and disrupting commuter services. The failures required operational workarounds to disembark passengers and equipment replacements. Both failures were caused when the power supply module stopped charging its associated backup battery bank.

Why it happened

- 1.3. Both outages were the result of weaknesses in the design, installation and operational oversight of a critical power supply system. In the first outage the failure in the power supply module was not addressed. This is because the design of the train control system's on-screen alarm was ineffective, and therefore it did not attract the operator's attention and alert them to the fact that there was an outage. This led to a backup battery discharging and the signalling computer shutting down.
- 1.4. Prior to the second outage, a replacement power supply module had been installed but it was unintentionally configured into a mode (calibration mode) that limited its output capacity and inhibited its alarms. The backup battery discharged until the signalling computer shut down. This time the power supply module alarm output signal did not activate, which prevented the train control system from displaying an alarm to advise the operator.
- 1.5. KiwiRail project documentation and management standards had not been fully applied, which meant KiwiRail did not identify that the power supply module's spare capacity was less than what was required. Additionally, the operators had not been trained to respond to the power supply alarms when they were displayed on the train control system screen.

What we can learn

- 1.6. These incidents underscore the need for robust change management and independent technical review during major infrastructure upgrades involving safety-critical systems.
- 1.7. Alarm and information displays should be designed with human factors in mind to ensure that operators identify, understand and act upon safety-critical information. Operator training should align with new procedures and systems.

Who may benefit

- 1.8. Rail system owners and infrastructure managers, train control room operators and their trainers, engineers and designers of alarm and monitoring systems for high-

reliability infrastructure may benefit from the findings and recommendations in this report.

2 Factual information

Pārongo pono

Background

- 2.1. The Wellington station area had been controlled from 'A-Box'¹ with a manual signalling system since its construction in 1937. This system consisted of a 127-lever Westinghouse Brake and Signal Company power lever frame (see Figure 2).




Figure 2: Westinghouse Brake and Signal Company power lever frame located in A-Box
(Credit: KiwiRail)

- 2.2. This system was replaced over the 2024/25 Christmas holidays as part of the Wellington Station resignalling project. The replacement consisted of upgrading the signalling infrastructure and relocating the signallers from A-Box to the Wellington Regional Operations Centre (WROC). The Wellington Junction train control desk at WROC is shown in Figure 3.

¹ The name given to the staffed signal box next to the tracks in the Wellington Station approaches.



Figure 3: Wellington Junction train control desk

- 2.3. The resignalling was a complex project and involved 52 new railway signals, four equipment huts, 6 kilometres (km) of cabling route ducting, 2 km of new track, 14 new turnouts² and 23 new overhead line structures throughout the wider station area (Phillipsen, Kilby, & Cox, 2025). The resignalling project was led by KiwiRail, with the signalling scope of the project delivered by Siemens Mobility Pty Ltd (Siemens).
- 2.4. In 2025, on a standard weekday there were approximately 390 scheduled passenger train movements arriving and departing Wellington Station. Outside of the morning and evening travel peaks, excess trains were stored in the yards, which were near the station. During peak travel times there were approximately 45 trains per hour, and outside of the peak times there were approximately 22 trains per hour.
- 2.5. The movements of all trains in and out of Wellington Station, whether to the suburban stations of the Wellington commuter network or into adjacent yards, was controlled by the signaller at WROC.
- 2.6. Detailed knowledge of the track layout at Wellington Station is necessary to facilitate these movements. This knowledge is supported by a mimic screen, which shows the status of signalling and track equipment and the locations of trains within the Wellington station area (see Figure 4).

² A section of track allowing trains to switch from one track to another.




Figure 4: Train control mimic screen

(Credit: KiwiRail)

- 2.7. The mimic screen was used by the signaller to set routes for trains to follow, and it displayed other critical information such as alarms about the network status.
- 2.8. The mimic display was created with a software application called RealFlex and displayed on a large computer screen. It provided the operator's user interface to KiwiRail's train control system.
- 2.9. During times when there were fewer passenger service trains running in the station area, the Wellington Junction desk was not occupied by a signaller. Instead, the Wellington regional train controller monitored the area.
- 2.10. The train control system in the Wellington area was a computer-based interlocking system that used Westrace controllers³ manufactured by Siemens.
- 2.11. The computer-based interlocking system consisted of multiple Westrace controllers distributed around the rail network. These controllers were connected to the rail track and signals and operated remotely through a RealFlex user interface centred on the mimic screen.
- 2.12. KiwiRail was in the process of upgrading its train control system at the time of the incident. This upgrade would replace the RealFlex user interface with a new rail traffic management system called ICONIS, set to be used in the Wellington station area from October 2025.

³ The Westrace controller is a modular, computer-based interlocking control system that was installed to manage and control train movements on the railway in Wellington Station. It can be thought of as a computer that uses logic to control switches and signals to ensure trains can move safely and avoid collisions.

Narrative

First occurrence

- 2.13. From before 0200⁴ on 27 March 2025, a visual alarm was regularly displayed at the WROC workstation for the Wellington regional and junction desks that stated 'WESTRACE HEALTH' (see Figure 5). That alarm was displayed on train control's mimic screen for about five seconds, every eight minutes until the power outage occurred.




Figure 5: Wellington Junction train control mimic screen with alarm displaying
(Credit: KiwiRail)

- 2.14. The WESTRACE HEALTH alarm indicated that there was a power supply problem within the computer-based interlocking system in the Wellington station area. The operators were not aware that this alarm existed prior to the event.
- 2.15. At 0430 on 27 March 2025 the rostered signaller began their shift at WROC. Prior to the signaller beginning their shift, the Wellington station area was controlled by the Wellington regional desk.
- 2.16. Between 0536 and 0550 the signaller set routes for four trains to depart the station. During this period the visual power supply alarm was displayed twice and not seen by the signaller.
- 2.17. At 0558, the signaller set the route for the first passenger train arrival of the day at the station.
- 2.18. At 0559, the signaller lost the ability to set routes through most of the Wellington station area due to the interlocking system losing power. All the signals in the area reverted to red to stop all train movements.
- 2.19. Without the ability to move trains into the station platforms, the next scheduled arrivals were held at suburban stations. Passengers were disembarked to find

⁴ Times used in this report are New Zealand Daylight Time (Universal Time Coordinated + 13 hours) and are expressed in 24-hour mode

alternative transport. The only train that was within the station limits was moved through the area under the signaller's verbal authority to allow its passengers to disembark on one of the platforms at Wellington Station.

- 2.20. Signalling technicians were called out to identify and resolve the fault. They found that a power supply module in equipment hut M0005, Rack A, had failed. They replaced the power supply module and the train control system gradually returned to normal. Train services were back running to usual schedules by about 0830.

Second occurrence

- 2.21. On 14 May 2025 at 1730, train control experienced further intermittent signal failures at Wellington Station. Trains were moved slowly and safely within KiwiRail's rules and procedures, until 1812, when the signalling system in Wellington failed.
- 2.22. Prior to the failure, no alarms were visually or audibly presented on the train control mimic screen to indicate that there was a problem with the power supply system.
- 2.23. The signals maintainer was called out to identify and resolve the fault. They found that the power supply module they had replaced in equipment hut M0005, Rack A, on 27 March 2025 had failed. It was replaced, and trains were operating normally by 1845.
- 2.24. On the second occasion, the failure was later identified to have been due to the power supply module being unintentionally switched to calibration mode. This was a factory test setting, not intended for field use, that limited the output power of the power supply module to approximately 50 per cent of its selected capacity.⁵ Calibration mode also inhibited the failure alarm signals from the power supply module.
- 2.25. This reduction in the power supply module's output capacity meant that it could not support the standing load and maintain the charge current to the battery bank. If the power supply module was unable to supply the load current, it would protect itself by reducing output voltage then shutting down. The backup batteries slowly discharged. Without the batteries providing supplementary power to the system, the Westrace controller had insufficient power to operate and, as a result, it shut down.

Power supply module

- 2.26. Four Westrace controllers were installed in equipment huts around the Wellington station area. The equipment huts were powered from a generator-backed ring main.⁶ Inside each hut, the AC supply was converted to DC by a power supply module.⁷ This power supply module float charged⁸ a battery bank and provided standing load⁹ to other elements of the railway system (see Figure 6).

⁵ The output power could be selected in steps from 500 watt to 1000 watt.

⁶ A ring main is a closed loop wiring circuit which supplies power to multiple outlets from both directions.

⁷ Helios 110VAC/55VDC power supply type AMP-K3024

⁸ A float charge is a type of low voltage charging that supplies a continuous low voltage to a battery to maintain its fully charged state.

⁹ Standing load refers to a constant, sustained power draw in an electrical system.




Figure 6: Wellington Station signalling schematic

- 2.27. If the AC supply failed, the generator would take over. The batteries ensured that the signalling system continued to operate uninterrupted until the generator connected to the ring main.
- 2.28. The power supply module that failed was a standard product provided to Siemens by their supplier and used in the signalling system at Wellington Station.
- 2.29. The battery was expected to provide power during periods of high load demand that were greater than the power supply capacity. The battery would then recharge when the rail traffic reduced between peak travel times. This design was approved by KiwiRail as part of the Wellington Station resignalling project.

Personnel information

- 2.30. The Wellington signaller who was on duty during the first signalling system power outage had over 30 years' experience working in A-Box. They had received training for the transition to working at WROC and were competent for the role.

Previous occurrence

RO-2017-102 Signalling irregularity, Wellington Railway Station, 3 April 2017

- 2.31. A previous incident where the Commission made recommendations around change and design management was the investigation into signalling irregularities at Wellington Station in 2017.
- 2.32. During the morning peak period on 3 April 2017, a route was set for a train movement that was not physically possible due to the design configuration of the track alignment. However, the route was available to the signallers according to their mimic screen.
- 2.33. Due to this discrepancy, the train was directed into a section of track where there was the potential for a collision with an oncoming train. The driver realised that their train was routed down the incorrect track and stopped, but not before the train had entered a potential collision zone. There was no collision and no one was injured.

- 2.34. Following an investigation into the incident, the Commission recommended that KiwiRail review its change management processes for modifying and building new safety-critical systems, and ensure that these processes include a full failure mode effects analysis and functional testing before the new or modified systems are put into service.
- 2.35. In response to the recommendation, KiwiRail improved its processes for scoping, design and testing of significant changes to safety-significant control systems. This included:
- identification of potential failure modes in the scoping phase
 - formal documentation of issues discovered throughout the testing process
 - formal technical and user sign-off before implementation
 - post-implementation review and associated issues tracking to capture and resolve residual issues.

Organisational information

- 2.36. KiwiRail Holdings Limited (KiwiRail) is a New Zealand state-owned enterprise. It controls rail movements on the national rail network and maintains the railway infrastructure as the rail access provider.
- 2.37. Siemens Mobility Pty Ltd (Siemens) is an engineering solutions provider, specialising in the design, supply and maintenance of rail transport systems. Siemens was contracted by KiwiRail to design and deliver the signalling scope of the Wellington Station resignalling project.

3 Analysis Tātaritanga

Introduction

- 3.1. On 27 March 2025, and again on 14 May 2025, the signalling system at Wellington Station experienced outages that caused significant delays to commuter transport. The outages on both occasions were caused by different failures of the same battery charger and power supply module within equipment hut M0005, Rack A. Both failures were caused when the power supply module stopped charging its associated backup battery bank.
- 3.2. The power supply system included an alarm to alert train controllers and signallers to problems within the network. However, they were not aware of the existence of the power supply alarms. The ineffective alarm presentation meant that when the alarm activated, it did not draw the intended recipient's attention to the failure of the power supply unit.
- 3.3. The effect of the signalling system power outage on the rail network at Wellington Station was handled in a safe manner, due to the signals in the area reverting to red to stop all trains. However, the reliability of a signalling system is fundamental to its safe operation. Two power outages within the space of six weeks indicates a reliability problem within the signalling system. Reliability helps to eliminate safety risks from the operation of the signalling system before they have an opportunity to occur.
- 3.4. The Commission's investigation identified two safety issues:
 - KiwiRail's application of design and project management standards
 - the need to consider human factors in alarm presentation.
- 3.5. The following section analyses the circumstances surrounding the events to identify those factors that increased the likelihood of the events occurring or increased the severity of their outcome. It also examines any safety issues that have the potential to adversely affect future operations.

Why did the power supply module fail?

- 3.6. The power supply module was designed to float charge the battery bank while also providing power to the standing load from other items in the signalling system. Siemens design criteria for the size of the power supply was that its capacity must be greater than 10 per cent above the maximum estimated load to ensure it could operate as intended. KiwiRail advised that the battery bank was intended to supplement the power supply output with peak load current and provide all power during mains outages.
- 3.7. KiwiRail advised that the first occurrence when the power supply module failed was due to an internal component fault. It is not unusual for electronic systems to fail occasionally; therefore mitigation of the effect is usually part of the design. Typically, power supplies for critical equipment are monitored remotely and rated for more than the maximum load or duplicated to allow redundancy.

- 3.8. A remote alarm was generated when the power supply module failed, and the alarm was shown on the mimic screen at train control. However, the remote alarm was not noticed, and as a result the fault was not investigated.
- 3.9. After the power supply module failed, the battery bank kept the signals operational for several hours, but the battery voltage gradually dropped to a level where the Westrace controller was no longer able to operate. It shut down, resulting in the first signal outage.
- 3.10. The power supply module was replaced and the system tested. However, the Wellington signalling system failed with similar operational outcomes about six weeks later. On this occasion, the failure was due to the power supply module being unintentionally switched to calibration mode. KiwiRail described that as a factory setting that neither they nor Siemens knew existed.
- 3.11. The power supply module gave no indication that it had been switched to calibration mode. This mode was understood to have been selected by usual actions that a technician might carry out during normal installation of the power supply, made in a specific sequence. Siemens advised that a subsequent firmware upgrade to the power supply module will generate an alarm if it is switched to calibration mode during installation.
- 3.12. On the second occasion, the remote power supply alarm system did not activate as intended and the signaller did not receive any warning of the issue with the signalling system power supply. This was due to the power supply being in calibration mode. A remote alarm from another source was transmitted approximately 20 seconds before the failure.¹⁰
- 3.13. The Commission's review of the signalling system's electrical drawings and power supply load calculations for Rack A in equipment hut M0005 revealed that the installed power supply capacity was undersized. The power supply module's spare capacity was less than the design criteria set by Siemens.¹¹
- 3.14. This shortfall posed an operational risk, as the configuration of the DC power supply in Rack A may not support full system functionality under peak load conditions or over a longer term. The limited capacity increased the vulnerability to potential disruptions through an inadequate battery-backed DC power supply to safety-critical systems.

Design assurance process for safety-critical systems

Safety issue 1: The design and assurance process for the auxiliary power supply system was inadequate to ensure the continued operational functionality of the safety-critical signalling system.

- 3.15. The Westrace controller that provided the computer-based interlocking system was critical for the safety of trains and passengers travelling on the network. Its operation had been tested and was proven to operate in a very safe manner during its

¹⁰ There were several other alarms related to the power supply combined into a single remote alarm.

¹¹ The spare capacity for Rack A in equipment hut M0005 was 1.6%.

construction and commissioning. It was also proven to fail to a safe condition.¹² These two key factors were required to achieve its Safety Integrity Level 4¹³ rating.

- 3.16. To ensure that the signalling computer was not affected by mains power disturbances, its power supply was backed up by a generator and a battery. The power supply status was also monitored remotely 24/7 by train control to ensure a quick response to a fault.
- 3.17. The Commission found that the power supply system designed for this critical safety system had not adequately considered the reliability of DC power supply in equipment hut M0005, Rack A. The power supply module depended on the battery bank to supplement peak load current, but the battery backup was not treated as a critical subsystem for continued operation of the signalling system. The power supply module was configured as a float voltage battery charger and power supply with a fixed voltage output. The voltage was set to match the optimum float charge voltage per battery cell in the battery bank.
- 3.18. A reliable power supply and battery charging system for a critical safety system should have ample spare capacity to cover both the standing load and the charging load for the battery bank. It may also have additional features such as:
 - power supply module duplication to provide full power supply redundancy
 - isolation of the charger function from the standing load
 - charge current limiting or current control to ensure optimum battery bank recharge rate and sufficient capacity for the standing load
 - undervoltage shutdown to protect the batteries discharging to a level that could permanently damage them
 - a timed boost-charge system to recharge the battery quickly and stabilise the charge level across the battery's internal cells and across individual batteries in the battery bank
 - automatic battery discharge test function
 - remote monitoring to draw attention to a fault, demanding an operator response to clear an alarm.¹⁴
- 3.19. The arrangement of the contractual responsibilities for the design and supply of the interlocking system and its integration with the existing KiwiRail train control system was within KiwiRail's scope of control. The resignalling project as a whole involved multiple contracts and contractors with overlapping scopes of work and complicated integration at the interface boundaries. The project work would also have required considerable planning to coordinate equipment delivery, installation, commissioning and training over the Christmas shutdown period.
- 3.20. KiwiRail had standards in place for design and project management to ensure that engineering designs were fit for purpose and adequately reviewed. KiwiRail high-level

¹² Failing to a safe condition means that if any part of the system malfunctions it automatically defaults to the safest possible state, usually displaying a stop indication at all relevant signals.

¹³ Safety Integrity Level 4 is the highest level in the international functional safety standard (IEC61508/CENELEC). It is used in critical systems where failures have catastrophic potential, such as railway signalling.

¹⁴ This aspect is explored further in Safety issue 2.

design management principles were set out in G-PR-AL-9025 Design Management and were linked to all the associated KiwiRail standards.

- 3.21. The design management principle, G-PR-AL-9025, included processes to ensure that:
- a phased approach is used to develop the design, with approval from KiwiRail at each phase
 - there is documentation of the key phases, such as design reports, hazard identification studies, risk assessments and mitigations, peer reviews, testing and commissioning records
 - record of the verification and validation of the design is completed using the Design Review Sign-off Sheet.
- 3.22. KiwiRail provided limited evidence to the Commission that demonstrated the processes under the design management principle had been carried out in relation to the resignalling project, or that a peer review of the DC power supply design had been adequately completed.
- 3.23. Siemens had conducted an internal review of the power supply design. This design review covered the entire power supply system, including both the AC and DC power loading within each equipment hut and racks.
- 3.24. Siemens engaged a separate consultant to conduct a peer review of the AC power supply system. The reviewer provided a Declaration of Conformity for this part of the overall design, confirming that it met the appropriate parts of the New Zealand Electricity Regulations 2010. However, this peer review did not cover the DC power loading, which is where the undersized power supply module was located.
- 3.25. The DC power supply design calculations were all contained in Siemens' power supply design documentation and showed that the power supply module in Rack A in equipment hut M0005 did not meet the design criteria. The summary sheet with this document set showed that its latest version was the 'as-built' version, signed off in June 2025, three months after the first signalling outage.
- 3.26. KiwiRail also engaged an external consultant to review the AC power supply system. However, KiwiRail did not conduct their own peer review of the DC power supply design. If they had, it would **likely** have identified issues with the power supply module's capacity to both support the standing load and charge the battery bank. It may have also questioned the reliability of the design to support a critical safety system.
- 3.27. It is **very likely** that KiwiRail's design and project management standards were not appropriately applied for the Wellington Station resignalling project. The signalling system failed twice in a predictable and repetitive nature that was identifiable through a review of the power supply system as part of the application of KiwiRail's design and project management standards.

Effectiveness of the alarm system

Safety issue 2: The alarm system to alert train control operators that a fault existed in the signalling system that could affect train operations, was ineffective.

- 3.28. In safety-critical operating environments, equipment is monitored remotely to alert operators to any faults. Any such alarms would generally be presented in a way that

drew attention to them and required action. An alarm could be temporarily suppressed but only stopped once the source event had been rectified.

- 3.29. The signalling system at Wellington Station sent an alarm to indicate the internal fault, but that alarm was displayed in a way that did not draw attention to it. Recordings of the train control mimic screen show that the alarm had been repeating for more than four hours.

Considerations for effective alarm system design

- 3.30. Within a control room environment, alarm systems indicate an unexpected abnormal state of the system by providing visual and/or auditory stimulation to bring people's attention to the event and convey relevant information. Such alarms are usually intended to change the operator's psychological state to alert, so they are ready to respond appropriately (Liu, Hwang, Hsieh, Liang, & Chuang, 2016).
- 3.31. To be effective, alarm systems should, at a minimum, provide relevant information in a timely manner to the people who need to be alerted. Furthermore, well-designed visual displays consider human perception, cognitive models, and principles of attention and memory, and assist the operator in managing multiple individual alarms (Wickens, Gordon, Liu, & Lee, 2004) (Liu, Hwang, Hsieh, Liang, & Chuang, 2016).
- 3.32. This is especially important in a busy operational environment such as a train control centre, where signallers and train controllers must maintain their attention on a range of tasks, using multiple screens in dynamic situations.

The RealFlex alarm design

- 3.33. In the lead-up to the first outage, when the power supply module failed and stopped charging the battery bank, an alarm was triggered. This alarm was presented on the mimic screen at the Wellington Station and Wellington region train controllers' desks.
- 3.34. The alarm consisted of the words WESTRACE HEALTH in red font (see Figure 7). This text was displayed for five seconds at a time before disappearing, then reappearing after eight minutes. The alarm did not include an auditory component, which was reserved for safety-critical alarms. This alarm was not considered safety-critical. The power supply failure did not pose an immediate risk to operations as the signals reverted to red to stop all trains.




Figure 7: Alarm presentation

- 3.35. The Commission identified three issues with the alarm's presentation.
- 3.36. First, the alarm system only alerted those in the train control centre. Those with the ability and responsibility to address any power supply issue (for example the signal maintenance team) were not included in the alarm system. Even when the alarm was unacknowledged for several hours, the system was not configured to escalate the issue any further. As a result, signalling maintenance staff were wholly reliant on train control to notice the alarm and inform them of the issue.
- 3.37. Second, although the alarm activated as intended, interviews confirmed that no one working in the train control centre saw it. The Commission identified several contributing factors.
 - It was not visually conspicuous, particularly in the context of the complex mimic screen. The text was red, which contrasted with the other on-screen text (mostly blue or black). However the mimic screen also uses red lines to indicate live trains, reducing the visibility of the alarm text.
 - It was only visible on-screen for five seconds at a time, interspersed with eight-minute periods where the text was not visible. This meant that the text was only visible for one per cent of the time that the alarm was activated.
 - Generally, train controllers use the mimic screen to monitor trains and control signals, so their attention would have been on the lines rather than the top of the screen where the alarm was shown.
- 3.38. Third, even if they had seen the alarm, neither the train controllers or signaller had any knowledge about the alarm system, and the words WESTRACE HEALTH did not hold any meaning for them. They had not received any training on procedures for

responding to such an alarm. As a result, they did not understand the implications of the alarm. This shows that the alarm had not been subject to user testing, which may have highlighted the design issues outlined above.

- 3.39. The signaller, the train controllers and signal maintenance staff were unaware of the power supply issue until the outage occurred. The Commission found that it is **virtually certain** that this occurred due to:
- the inadequate alarm presentation
 - a lack of user training for the alarm system.

4 Findings

Ngā kitenga

- 4.1. When the power supply module failed due to an internal fault, the remote alarm that was generated and shown on the mimic screen at train control was not noticed. Consequently, the fault was not investigated. Eventually, the battery voltage dropped to a level where the Westrace controller was no longer able to operate and it shut down, resulting in the first signal outage.
- 4.2. On the second occasion, the remote power supply alarm system did not activate as intended and the signaller did not receive any warning of an issue with the signalling system power supply. This was due to the power supply being in calibration mode. A remote alarm from another source was transmitted approximately 20 seconds before failure.
- 4.3. The Commission's review of the signalling system's electrical drawings and power supply load calculations for Rack A in equipment hut M0005 revealed that the installed power supply capacity was undersized. The power supply module's spare capacity was less than the design criteria set by Siemens.
- 4.4. KiwiRail did not conduct their own peer review of the DC power supply design. If they had, it would **likely** have identified issues with the power supply module's capacity to both support the standing load and charge the battery bank. It may have also raised questions about the reliability of the design to support a critical safety system.
- 4.5. It is **very likely** that KiwiRail's design and project management standards were not appropriately applied for the Wellington Station resignalling project. The signalling system failed twice in a predictable and repetitive nature that was identifiable through a review of the power supply system as part of the application of KiwiRail design and project management standards.
- 4.6. The signaller, the train controllers and signal maintenance staff were unaware of the power supply issue until the outage occurred. The Commission found that it is **virtually certain** that this occurred due to:
 - the inadequate alarm presentation
 - a lack of user training for the alarm system.

5 Safety issues and remedial action

Ngā take haumarū me ngā mahi whakatika

General

- 5.1. Safety issues are an output from the Commission's analysis. They may not always relate to factors directly contributing to the accident or incident. They typically describe a system problem that could adversely affect future transport safety.
- 5.2. Safety issues may be addressed by safety actions taken by a participant; otherwise the Commission may issue a recommendation to address the issue.

Safety issue 1: The design and assurance process for the auxiliary power supply system was inadequate to ensure the continued operational functionality of the safety-critical signalling system.

- 5.3. Since the incidents, KiwiRail has implemented the following safety actions to address the power failures.
 - a Significant Improvement Notice was issued to ensure that both existing and new installations of the power supply module were not installed in calibration mode.
 - in partnership with Siemens, KiwiRail has redistributed some electrical loads within equipment hut M0005 to increase the power supply module's spare capacity in the equipment racks to meet their design criteria.
 - the decision was made to phase out the use of the power supply module that was used in the incident.
 - a suite of new standards was implemented that will improve the signalling design and assurance processes.
 - changes to their type approval process are being explored, to ensure issues related to product functionalities are considered.
- 5.4. In the Commission's view, these safety actions have addressed the safety issue. Therefore the Commission has not made a recommendation.

Safety Issue 2: The alarm system to alert train control operators that a fault existed in the signalling system that could affect train operations, was ineffective.

- 5.5. Since the incidents, KiwiRail has made significant improvements to the alarm display at the train control desks. The alarm faults page is now permanently displayed, and the design has been improved to ensure it captures the operator's attention. The alarm system has also been updated to include a visual alarm to alert the operator if the power supply module has been installed in calibration mode, along with further monitoring relays to ensure the output of the power supply is as required.
- 5.6. KiwiRail is also in the process of upgrading its train control and traffic management to the ICONIS system. The alarm displays will be further improved in this system as they will require the operator to acknowledge and action them before clearing. This is anticipated to be fully operational across the network by February 2027.
- 5.7. In the Commission's view, this safety action has addressed the safety issue. Therefore the Commission has not made a recommendation.

6 Recommendations Ngā tūtohutanga

General

- 6.1. The Commission issues recommendations to address safety issues found in its investigations. Recommendations may be addressed to organisations or people and can relate to safety issues found within an organisation or within the wider transport system that could contribute to future transport accidents and incidents.
- 6.2. In the interests of transport safety, it is important that recommendations are implemented without delay to help prevent similar accidents or incidents occurring in the future.
- 6.3. No new recommendations were issued.

7 Other safety lessons

Ngā akoranga matua

- 7.1. Major infrastructure upgrades to railway systems are complex projects due to their multidisciplinary nature. Careful design and project management are necessary to ensure risks at all stages of a project are adequately identified and managed.

8 Data summary

Whakarāpopoto raraunga

<i>Date and time</i>	first occurrence: 27 March 2025, 0559
	second occurrence: 14 May 2025, 1812
<i>Location</i>	Wellington Station
<i>Injuries</i>	nil
<i>Damage</i>	nil

9 Conduct of the inquiry

Te whakahaere i te pakirehua

- 9.1. On 27 March 2025, the Commission learned of the incident through media reports. On 28 March 2025, the New Zealand Transport Agency notified the Commission of the occurrence. The Commission subsequently opened an inquiry under section 13(1) of the Transport Accident Investigation Commission Act 1990 and appointed an investigator in charge.
- 9.2. A second incident occurred on the 14 May 2025, which the Commission included within this inquiry.
- 9.3. The Commission investigators conducted interviews with KiwiRail staff directly involved in both incidents and visited various sites to obtain further information.
- 9.4. The Commission obtained records and information from sources that included:
 - technical specifications and electrical drawings for the signalling system at Wellington Station
 - recordings of the train control mimic screens on the day of the incidents.
- 9.5. The Commission engaged a subject matter expert from Australia to assist with the inquiry.
- 9.6. On 24 February 2026, the Commission approved a draft report for circulation to five interested parties for their comment.
- 9.7. Two interested parties provided detailed submissions and four interested parties replied that they had no comment. Any changes as a result of the submissions have been included in the final report.
- 9.8. On 27 May 2026, the Commission approved the final report for publication.

Abbreviations

Whakapotonga

km kilometre

WROC Wellington Regional Operations Centre

Glossary

Kuputaka

A-Box	the name given to the staffed signal box next to the tracks in the Wellington Station approaches
interlocking	a safety-critical system designed to prevent conflicting movements of rail vehicles and ensure the safe operation of railway networks
mimic screen	a digital display which graphically displays the state of the various components of the railway, such as switches, signals and trains
signaller	the person who directly controls signals at an interlocked station; may also be the train controller
train controller	the person who controls the movement of all trains and authorisation of maintenance occupancies within a specific area on the controlled network
Westrace controller	a digital control system used to manage and control train movements on the railway in Wellington Station. It can be thought of as a computer that uses logic to control switches and signals to ensure trains can move safely and avoid collisions

Citations

Ngā tohutoru

Liu, K.-H., Hwang, S.-L., Hsieh, M.-H., Liang, S.-F., & Chuang, C.-F. (2016). Systematic layout planning in human-system interface: An evaluation of alarm displays with spatial proximity for accidents diagnosis of advanced boiling water reactor. *International Journal of Industrial Ergonomics*, 51, 30–52.

Phillipsen, D., Kilby, M., & Cox, D. (2025). Enhancing Railway Systems: A Multidisciplinary Approach to New Zealand's Most Complex Resignalling. *Conference of Railway Excellence*.

Wickens, C., Gordon, S., Liu, Y., & Lee, J. (2004). *An introduction to human factors engineering* (Vol. 2). Upper Saddle River, NJ, USA: Pearson Prentice Hall.

Kōwhaiwhai - Māori scroll designs

TAIC commissioned its four kōwhaiwhai, Māori scroll designs, from artist Sandy Rodgers (Ngāti Raukawa, Tūwharetoa, MacDougal). Sandy began from thinking of the Commission as a vehicle or vessel for seeking knowledge to understand transport accident tragedies and how to avoid them. A 'waka whai mārama' (i te ara haumarū) is 'a vessel/vehicle in pursuit of understanding'. Waka is a metaphor for the Commission. Mārama (from 'te ao mārama' – the world of light) is for the separation of Rangitāne (Sky Father) and Papatūānuku (Earth Mother) by their son Tāne Māhuta (god of man, forests and everything dwelling within), which brought light and thus awareness to the world. 'Te ara' is 'the path' and 'haumarū' is 'safe' or 'risk free'.

Corporate: Te Ara Haumarū - the safe and risk free path



The eye motif looks to the future, watching the path for obstructions. The encased double koru is the mother and child, symbolising protection, safety and guidance. The triple koru represents the three kete of knowledge that Tāne Māhuta collected from the highest of the heavens to pass their wisdom to humanity. The continual wave is the perpetual line of influence. The succession of humps represents the individual inquiries.

Sandy acknowledges Tāne Māhuta in the creation of this Kōwhaiwhai.

Aviation: Ngā hau e whā - the four winds



To Sandy, 'Ngā hau e whā' (the four winds), commonly used in Te Reo Māori to refer to people coming together from across Aotearoa, was also redolent of the aviation environment. The design represents the sky, cloud, and wind. There is a manu (bird) form representing the aircraft that move through Aotearoa's 'long white cloud'. The letter 'A' is present, standing for a 'Aviation'.

Sandy acknowledges Ranginui (Sky father) and Tāwhirimātea (God of wind) in the creation of this Kōwhaiwhai.

Maritime: Ara wai - waterways



The sections of waves flowing across the design represent the many different 'ara wai' (waterways) that ships sail across. The 'V' shape is a ship's prow and its wake. The letter 'M' is present, standing for 'Maritime'.

Sandy acknowledges Tangaroa (God of the sea) in the creation of this Kōwhaiwhai.

Rail: rerewhenua - flowing across the land



The design represents the fluid movement of trains across Aotearoa. 'Rere' is to flow or fly. 'Whenua' is the land. The koru forms represent the earth, land and flora that trains pass over and through. The letter 'R' is present, standing for 'Rail'.

Sandy acknowledges Papatūānuku (Earth Mother) and Tāne Mahuta (God of man and forests and everything that dwells within) in the creation of this Kōwhaiwhai.



Transport Accident Investigation Commission

**Recent Rail Occurrence reports published by
the Transport Accident Investigation Commission
(most recent at top of list)**

RO-2024-103	Bridge 57 Main South Line, Pier 8 collapse, Rangitata, 12 April 2024
RO-2025-103	Mainline shunt, Train 170S, Signal passed at danger and near miss with passenger train, Westfield, Auckland, 1 February 2025
RO-2025-102	Y20 shunt, runaway rail vehicle collision and near miss with rail crew, Port Chalmers, Dunedin, 23 January 2025
RO-2024-104	Freight train MR1, Signal passed at danger and near miss with HRV, Kereone Station, 2 August 2024
RO-2025-101	Train 931, safe working irregularity, 553.82 km Main South Line, Maitāwhiri, 12 January 2025
RO-2023-105	Derailment of Tamper 703, Purewa tunnel, Auckland, 9 October 2023
RO-2024-102	Freight Train 882, near miss with track workers, Main South Line, Hornby 27 km, 7 March 2024
RO-2023-106	Passenger train 804, TranzAlpine, train parting, Arthur's Pass, 17 December 2023
RO-2024-101	Loaded coal train 850, signal passed at danger, Cora Lynn, Midland line, 27 February 2024
RO-2023-104	Passenger train (Te Huia) signal passed at danger and potential conflict, Penrose, Auckland, 17 June 2023
RO-2021-104	Passenger train 6205, train derailment, Kāpiti, 17 August 2021
RO-2023-102	Freight train 360, derailment, Te Puke, 29 January 2023
RO-2023-101	Hi rail vehicle collision near Te Puna, 86.43 km East Coast Main Trunk Line, 10 January 2023
RO-2023-103	Safe working irregularity, 3.85km, Johnsonville line, tunnel 5, 4 May 2023
RO-2022-104	Shunt train L51 and heavy goods vehicle, level crossing collision and derailment, Whangārei, 7 December 2022

Price \$14.00

ISSN 2815-889X (Print)
ISSN 2815-8903 (Online)