



Transport Accident
Investigation
Commission

Final Interim report

Rīpoata Whakamutunga Mō Nāianeī

Maritime inquiry MO-2026-201
Passenger vessel, Black Cat
Grounding
Entrance to Akaroa Harbour, New Zealand
31 January 2026

August 2026



The Transport Accident Investigation Commission

Te Kōmihana Tirotiro Aituā Waka

No repeat accidents – ever!

“The principal purpose of the Commission shall be to determine the circumstances and causes of accidents and incidents with a view to avoiding similar occurrences in the future, rather than to ascribe blame to any person.”

Transport Accident Investigation Commission Act 1990, s4 Purpose

The Transport Accident Investigation Commission is an independent Crown entity and standing commission of inquiry. We investigate selected maritime, aviation and rail accidents and incidents that occur in New Zealand or involve New Zealand-registered aircraft or vessels.

Our investigations are for the purpose of avoiding similar accidents and incidents in the future. We determine and analyse contributing factors, explain circumstances and causes, identify safety issues, and make recommendations to improve safety. Our findings cannot be used to pursue criminal, civil, or regulatory action.

At the end of every inquiry, we share all relevant knowledge in a final report. We use our information and insight to influence others in the transport sector to improve safety, nationally and internationally.

Commissioners

Chief Commissioner	David Clarke
Deputy Chief Commissioner	Stephen Davies Howard
Commissioner	Paula Rose, QSO
Commissioner (from 19 June 2026)	Aedeen Boadita-Cormican

Key Commission personnel

Chief Executive	Martin Sawyers
Chief Investigator of Accidents	Louise Cook
Investigator-in-Charge for this inquiry	Robert Thompson
Commission General Counsel	Sid Wellik

Notes about Commission reports

Kōrero tāpiri ki ngā pūrongo o te Kōmihana

Nature of this interim report

The Commission issues interim reports in the initial stages of an investigation. The interim report presents the facts and circumstances established up to this point in the Commission's inquiry. The Commission may issue an interim report in line with international guidance where inquiries are complex and ongoing.

Final report

After it completes its inquiry, the Commission will issue a final report on the incident. That report will contain an analysis of the facts of the incident, findings and recommendations. The information contained in the Commission's final report may differ from the information contained in this interim factual report.

Photographs, diagrams, pictures

The Commission owns the photographs, diagrams and pictures in this report unless otherwise specified.

Verbal probability expressions

For clarity, the Commission uses standardised terminology where possible.

One example of this standardisation is the terminology used to describe the degree of probability (or likelihood) that an event happened, or a condition existed in support of a hypothesis. The Commission has adopted this terminology from the Intergovernmental Panel on Climate Change and Australian Transport Safety Bureau models. The Commission chose these models because of their simplicity, usability, and international use. The Commission considers these models reflect its functions. These functions include making findings and issuing recommendations based on a wide range of evidence, whether or not that evidence would be admissible in a court of law.

Terminology	Likelihood	Equivalent terms
Virtually certain	> 99% probability of occurrence	Almost certain
Very likely	> 90% probability	Highly likely, very probable
Likely	> 66% probability	Probable
About as likely as not	33% to 66% probability	More or less likely
Unlikely	< 33% probability	Improbable
Very unlikely	< 10% probability	Highly unlikely
Exceptionally unlikely	< 1% probability	



Figure 1: *Black Cat*
(Credit: Black Cat Cruises)




Figure 2: Akaroa Harbour and grounding location
 (Credit: Land Information New Zealand Toitū Te Whenua)

Contents

Rārangi take

1	Executive summary	1
	What happened.....	1
2	Factual information	2
	Narrative.....	2
	Vessel information.....	9
	Personnel information	9
3	Data summary	10
4	Conduct of the inquiry	11
	Abbreviations.....	12
	Glossary	13

Figures

Figure 1: <i>Black Cat</i>	iii
Figure 2: Akaroa Harbour and grounding location	iv
Figure 3: Location of <i>Black Cat</i>'s helm stations	2
Figure 4: <i>Black Cat</i>'s track from Akaroa main wharf to Scenery Nook	3
Figure 5: <i>Black Cat</i>'s track from Scenery Nook to the beach at Nikau Palm Gully	4
Figure 6: Profile of the <i>Black Cat</i>	5
Figure 7: The <i>Black Cat</i>'s port-side engine room showing the engine	5
Figure 8: Evacuation of passengers from the <i>Black Cat</i>	7
Figure 9: The <i>Black Cat</i> shortly after the passengers were evacuated	7
Figure10: The <i>Black Cat</i> as the master navigated towards the beach, with a jet ski standing by	8

1 Executive summary

Tuhinga whakarāpopoto

- 1.1. The Commission's investigation is ongoing. This interim report presents the facts and circumstances established up to this point in the Commission's inquiry. Upon completion of the inquiry, the Commission will issue a final report on the accident. That final report will contain an analysis of the facts of the accident, findings, safety issues and recommendations (if any).
- 1.2. This was a serious accident, where 41 people were at risk of significant harm, drawing heightened public interest. This interim report has been prepared to provide timely information on the accident to the maritime industry and to the public, for clarity and to avoid similar maritime incidents or accidents in the future.

What happened

- 1.3. The *Black Cat* was a 17-metre (m) catamaran owned by Black Cat Cruises and operated out of Akaroa, New Zealand.
- 1.4. On the morning of 31 January 2026, the *Black Cat* was conducting a scenic cruise in the vicinity of Akaroa Harbour with 38 passengers and 3 crew on board.
- 1.5. The weather was calm. While approaching Archway Rock, the vessel struck a submerged object. The vessel's position at the time of impact aligned with a charted submerged rock of an unknown depth.
- 1.6. The starboard hull was ruptured and began flooding with seawater. In response, the crew attempted to activate an additional bilge pumping system. The crew were not confident in how to operate the system correctly, so the pump was not engaged.
- 1.7. The master navigated *Black Cat* into Akaroa Harbour to facilitate a safe evacuation. While in the harbour, the vessel's steering and starboard engine had stopped operating and the emergency steering was not responding. By this point the *Black Cat* had developed a significant starboard list.
- 1.8. The passengers were safely evacuated onto responding vessels before the Coastguard unsuccessfully attempted to dewater the vessel.
- 1.9. Trying to save the vessel, the master attempted to manoeuvre *Black Cat* towards the beach when it ran aground.
- 1.10. All passengers and crew were safely transferred back to Akaroa without injury.

2 Factual information

Pārongo pono

Narrative

- 2.1. On the morning of 31 January 2026, the *Black Cat* was moored in Akaroa Harbour. It was scheduled to conduct a scenic cruise in and around Akaroa Harbour. This was a regular two-hour cruise during which the *Black Cat* crew embarked passengers at Akaroa main wharf and the vessel visited various locations to view wildlife and scenery. The master determined the route for each trip based on the conditions on the day.
- 2.2. At about 1007¹ the vessel was moved from the mooring to its berth on the Akaroa main wharf, ready for the day's operations. The master and two crew (C1 and C2) began boarding the 38 passengers.
- 2.3. At about 1045, once the passengers had finished boarding, the master manoeuvred the vessel off the berth and departed. The master delivered the safety briefing, which included the layout of the vessel, location of emergency equipment and their expectations in the event of an emergency.
- 2.4. The master operated the *Black Cat* from the central bridge helm station (see Figure 3) and navigated south, following the eastern coast of Akaroa Harbour (see Figure 4). At about 1104, the *Black Cat* arrived at Spotted Shag Rookery and spent about 13 minutes there while the master delivered commentary for the passengers regarding the area and what could be seen.




Figure 3: Location of *Black Cat*'s helm stations
(Credit: Michal Klajban;² image edited to blur people's faces)

¹ Times in this report are in New Zealand Daylight Time (Universal Coordinated Time +13 hours) expressed in a 24-hour format

² Image licensed under Creative Commons Attribution-Share Alike 4.0 International.




Figure 4: *Black Cat*'s track from Akaroa main wharf to Scenery Nook

- 2.5. The *Black Cat* continued south and at about 1125 arrived at Cathedral Cave, where it spent about 10 minutes, with more commentary from the master.
- 2.6. The weather was calm and the master decided to navigate outside Akaroa Harbour and visit Scenery Nook, on the south coast (see Figure 4). The *Black Cat* exited the Akaroa Harbour heads and arrived near the entrance to Scenery Nook at about 1152.
- 2.7. On approach to Scenery Nook, the master moved to the starboard bridge wing helm station to manoeuvre the vessel close to known rocks.
- 2.8. While at Scenery Nook, the master decided to visit Archway Rock (see Figure 5), a geological feature, on the way back to Akaroa. At about 1207, the *Black Cat* left Scenery Nook and the master moved back to the central bridge helm station so they could look at the chart plotter regarding their intended route. The master then moved to the port bridge wing helm station and navigated toward Archway Rock.




Figure 5: Black Cat's track from Scenery Nook to the beach at Nikau Palm Gully

- 2.9. At about this time, C1 and C2 were talking in *Black Cat's* main cabin (see Figure 6). While looking out the window, C1 noticed that the vessel was approaching Archway Rock from an unusual direction. They told C2 they were going to the bridge to discuss their concern with the master. Meanwhile, C2 went to the vessel's foredeck to meet with passengers and take photos of the view.
- 2.10. At about 1212, C2 used their mobile phone to take photos³ of Archway Rock. A few seconds later a bump was felt and there was a scraping sound. C2 immediately went to the bridge to join the master and C1 to discuss the event. The geo-location data⁴ aligned with a submerged rock of an unknown depth on the chart⁵ (see Figure 5).
- 2.11. The master thought they might have hit the float of a crayfishing pot but couldn't see anything in the water. About one minute after the scraping sound the bilge alarm activated.

³ The photos included geo-location data.

⁴ The vessel's position was determined from two independent sources: geo-location data from the photos taken immediately before the grounding and a GPS tracker that was installed onboard the *Black Cat*.

⁵ This rock symbol represents an 'underwater rock over which the depth is unknown, but which is considered dangerous to surface navigation' (UK Hydrographic Office, 2026, *Admiralty Chart 5011 – 'Symbols and Abbreviations used on Admiralty Paper Charts'*).

- 2.12. The master instructed C1 to take the *Black Cat*'s helm to enable them to check the vessel's bilges. The master went to the starboard aft deck, opened the hatch and climbed down into the aft compartment (see Figure 6). They opened the starboard engine room's bulkhead door and saw that water had entered the engine room and the water level was around the top of the engine (see Figure 7). The master immediately closed and secured the bulkhead door and made their way back up to the bridge.




Figure 6: Profile of the *Black Cat*




Figure 7: The *Black Cat*'s port-side engine room showing the engine⁶

- 2.13. As the *Black Cat* passed the harbour entrance, smoke or steam was visibly entering the main cabin from the engine room and passengers became aware that something was wrong.
- 2.14. Meanwhile, the master arrived on the bridge and notified two company vessels that were nearby by calling them on the very-high-frequency (VHF) radio. The master intended to get the *Black Cat* near a safe beach to facilitate beaching or

⁶ The layout of the port engine room is essentially a mirror image of the starboard engine room.

evacuation of the vessel. There were limited suitable beaches in the area, and the master chose the beach at Nikau Palm Valley to either anchor or beach the vessel. The master began navigating the vessel towards that location.

- 2.15. On the bridge the steering had stopped working, along with the CCTV and PA systems. The starboard engine and propulsion system had also stopped operating. The master and C1 could not activate the emergency steering system that was also located in the starboard hull.
- 2.16. The master instructed the crew to go to the aft compartment (on the port side) and start the engine-driven bilge-pump system. C1 and C2 went to the bilge-pump control station in the aft compartment but were not confident in how to operate the bilge-pump system.
- 2.17. C1 and C2 left the aft compartment and began reassuring the passengers and getting them into lifejackets. C1 and C2 began mustering the passengers to the bridge deck level on the port side. It took about 10 to 15 minutes for the passengers and crew to finish putting on lifejackets.
- 2.18. By this time, several other vessels had responded to the earlier radio call and had arrived at the *Black Cat's* location ready to assist.
- 2.19. There was significant radio traffic. Over radio, the master requested other stations to limit traffic so the *Black Cat* could communicate with responding vessels. At about 1232, the master used VHF radio to broadcast a Pan-Pan⁷ urgency signal, which stated the *Black Cat* with 38 people on board was taking on water just south of Dan Rogers [bluff].
- 2.20. By this stage the smoke or steam was filling the *Black Cat's* cabin. The vessel was listing heavily to starboard, with some water on deck on the starboard aft deck, and most of the passengers were on the bridge deck on the port side.
- 2.21. The master instructed the crew to move the passengers down onto the main deck in preparation to evacuate the vessel. The evacuation began shortly after (see Figure 8).
- 2.22. Several vessels were standing by to assist. The smaller vessels ferried groups of passengers from the port stern of the *Black Cat* onto the larger vessels. The evacuation of passengers and C2 was completed without significant issue by 1240.

⁷ A Pan-Pan urgency signal is a standardised radio-telephony phrase used to indicate a very urgent message concerning safety is to follow, but there is no immediate danger requiring distress assistance.



Figure 8: Evacuation of passengers from the *Black Cat*

(Credit: TVNZ (via RNZ) taken by a witness)

- 2.23. The master and C1 remained on board following the evacuation of all passengers. C1 checked there were no passengers still onboard and reported this information to the master. The master then continued to navigate the *Black Cat* towards the beach at Nikau Palm Gully. With only the port-side propulsion working, the vessel naturally turned to starboard. The master countered this starboard turn by occasional use of astern power.
- 2.24. A local Coastguard vessel, the *Ihenga Rescue*, was exercising just outside Akaroa Harbour, with five Coastguard volunteers and two potential recruits on board. When the Coastguard crew heard the Pan-Pan radio transmission they proceeded into Akaroa Harbour, arriving at the *Black Cat*'s location shortly before the evacuation of passengers finished.
- 2.25. The Coastguard crew noticed that the *Black Cat* was settling lower in the water (see Figure 9). The *Ihenga Rescue* carried a portable petrol-powered water pump, which the Coastguard master decided to use onboard the *Black Cat* to help clear water from the vessel.



Figure 9: The *Black Cat* shortly after the passengers were evacuated

- 2.26. Once the passenger evacuation was complete, one of the Coastguard volunteers and one of the potential recruits boarded the *Black Cat* via the port stern door with the pump equipment.

- 2.27. Once on board they spoke briefly with C1 who assisted them. The Coastguard volunteer and the potential recruit then set up the pump. They could see water sloshing on the starboard side of the aft deck area and proceeded to pump it overboard.
- 2.28. Intending to beach the *Black Cat*, the master continued navigating towards the beach as the starboard hull settled lower in the water and the vessel listed more (see Figure 10). Eventually seawater started flowing over the top of the bulwark⁸ into the aft deck area and C1, the Coastguard volunteer and the Coastguard's potential recruit decided to evacuate from the *Black Cat* to nearby vessels.



Figure10: The *Black Cat* as the master navigated towards the beach, with a jet ski standing by

- 2.29. At about 1247, while the *Black Cat* was approaching the beach at Nikau Palm Gully, it grounded again. The master shut down the port engine and evacuated the vessel onto a jet ski that was standing by.
- 2.30. All passengers and crew were safely transferred back to Akaroa with no reported injuries.
- 2.31. A Tier 2 (regional) oil-spill response⁹ was declared by Environment Canterbury¹⁰ at 1345. A salvage operation was initiated over the following days by Black Cat Cruises and their protection and indemnity club.¹¹ The salvage operation failed to refloat and recover the vessel, which broke up in heavy weather conditions. By

⁸ A bulwark is a solid vertical extension of the hull above the deck edge that acts as a protective barrier for crew and equipment.

⁹A regional, council-led oil-spill response for pollution containment and clean-up that does not include search and rescue functions.

¹⁰ Canterbury Regional Council.

¹¹ A mutual marine insurance association joined by shipowners to cover liabilities and risks that ordinary hull insurance usually does not.

19 March 2026, all safe-to-collect vessel fragments were recovered and the Tier 2 response continued as a monitoring and observation presence. Environment Canterbury informed the Commission that the environmental impact of the accident was minimal.

Vessel information

- 2.32. The *Black Cat* was a 17 m aluminium alloy catamaran built in 1994 to service the Whitsunday Islands in Queensland, Australia. Black Cat Cruises brought it into service in Lyttelton, New Zealand, and began operating from Akaroa in 2004.
- 2.33. The *Black Cat* was powered by two Yanmar 6HY diesel engines, one in each hull. Each engine was connected to a conventional shaft and propeller. Steering was provided by conventional rudders, one on each hull.
- 2.34. The *Black Cat* was fitted with four independent bilge-pumping systems:
 - a 24 V electric-powered pump
 - a 230 V electric-powered pump
 - an engine-driven pump
 - a manually operated bilge pump.

Personnel information

- 2.35. The master was issued an Australian Skipper 3¹² certificate of competency in 1988 when working on the Great Barrier Reef. They worked on several different vessels in various locations until they moved to New Zealand. They were issued a New Zealand Inshore Launch Master certificate of competency in 2013. They joined Black Cat Cruises in February 2025 and began sailing as master of the *Black Cat* on 1 December 2025.
- 2.36. C1 had worked as crew in Doubtful Sound and Lake Manapouri for three years before joining Black Cat Cruises as crew on board *Black Cat* in 2012.
- 2.37. C2 had worked at Black Cat Cruises in the office during the summer season of 2025, and then as crew in November 2025 onboard the *Black Cat*.

¹² Skipper 3 was a former Australian commercial master's qualification for operating small vessels in limited near-coastal waters.

3 Data summary

Whakarāpopoto raraunga

Vehicle particulars

Name:	<i>Black Cat</i>
Type:	passenger catamaran
Limits:	inshore
Length:	17.3 m
Beam:	7.1m
Built:	1994
Propulsion:	2 x Yanmar 6HY diesel engines, each driving a conventional shaft and propeller
MNZ number:	126264
Owner/operator:	Black Cat Cruises
Port of registry:	Lyttelton

Date 31 January 2026

Location Entrance to Akaroa Harbour, New Zealand

Persons involved 38 passengers and 3 crew

Injuries None reported

Damage Total loss of vessel

4 Conduct of the inquiry

Te whakahaere i te pakirehua

- 4.1. On 31 January 2026, Maritime New Zealand notified the Commission of the occurrence. The Commission subsequently opened an inquiry under section 13(1) of the Transport Accident Investigation Commission Act 1990 and appointed an Investigator-in-Charge.
- 4.2. A protection order was issued on 31 January 2026, which related to the *Black Cat*'s wreckage, electronics and navigational equipment and logbooks.
- 4.3. On 1 February 2026, Commission investigators travelled to Akaroa to gather evidence and conduct interviews, returning to Wellington on 4 February.
- 4.4. On 28 May 2026, the Commission approved a draft interim report for circulation to four interested parties for their comment and to four others to ensure factual accuracy.
- 4.5. The Commission received three responses, of which all were submissions. Any changes as a result of these submissions have been included in this final interim factual report.
- 4.6. On 31 July 2026, the Commission approved this final interim report for publication.
- 4.7. The Commission's investigation is ongoing. Upon completion of the inquiry, the Commission will issue a final report on the accident. That final report will contain an analysis of the facts of the accident, findings, safety issues and recommendations (if any).

Abbreviations

Whakapotonga

C1	Crew member 1
C2	Crew member 2
CCTV	Closed-circuit television
PA	Public address
VHF	Very-high frequency

Glossary

Kuputaka

Bulwark	A solid vertical extension of the hull above the deck edge that acts as a protective barrier for crew and equipment
Closed-circuit television	A system that uses cameras to monitor and record activity to a limited set of screens
Public address system	An audio system used to amplify and broadcast announcements or messages to a group of people
Pan-Pan urgency signal	A standardised radio-telephony phrase used to indicate a very urgent message concerning safety is to follow, but there is no immediate danger requiring distress assistance
Protection and indemnity club	A mutual marine insurance association joined by shipowners to cover liabilities and risks that ordinary hull insurance usually does not
Skipper 3	A former Australian commercial master's qualification for operating small vessels in limited near-coastal waters
Tier 2 oil-spill response	In New Zealand, a regional, council-led oil-spill response for pollution containment and clean-up that did not include search and rescue functions

Kōwhaiwhai - Māori scroll designs

TAIC commissioned its four kōwhaiwhai, Māori scroll designs, from artist Sandy Rodgers (Ngāti Raukawa, Tūwharetoa, MacDougal). Sandy began from thinking of the Commission as a vehicle or vessel for seeking knowledge to understand transport accident tragedies and how to avoid them. A 'waka whai mārama' (i te ara haumarū) is 'a vessel/vehicle in pursuit of understanding'. Waka is a metaphor for the Commission. Mārama (from 'te ao mārama' – the world of light) is for the separation of Rangitāne (Sky Father) and Papatūānuku (Earth Mother) by their son Tāne Māhuta (god of man, forests and everything dwelling within), which brought light and thus awareness to the world. 'Te ara' is 'the path' and 'haumarū' is 'safe' or 'risk free'.

Corporate: Te Ara Haumarū - the safe and risk free path



The eye motif looks to the future, watching the path for obstructions. The encased double koru is the mother and child, symbolising protection, safety and guidance. The triple koru represents the three kete of knowledge that Tāne Māhuta collected from the highest of the heavens to pass their wisdom to humanity. The continual wave is the perpetual line of influence. The succession of humps represents the individual inquiries.

Sandy acknowledges Tāne Māhuta in the creation of this Kōwhaiwhai.

Aviation: Ngā hau e whā - the four winds



To Sandy, 'Ngā hau e whā' (the four winds), commonly used in Te Reo Māori to refer to people coming together from across Aotearoa, was also redolent of the aviation environment. The design represents the sky, cloud, and wind. There is a manu (bird) form representing the aircraft that move through Aotearoa's 'long white cloud'. The letter 'A' is present, standing for a 'Aviation'.

Sandy acknowledges Ranginui (Sky father) and Tāwhirimātea (God of wind) in the creation of this Kōwhaiwhai.

Maritime: Ara wai - waterways



The sections of waves flowing across the design represent the many different 'ara wai' (waterways) that ships sail across. The 'V' shape is a ship's prow and its wake. The letter 'M' is present, standing for 'Maritime'.

Sandy acknowledges Tangaroa (God of the sea) in the creation of this Kōwhaiwhai.

Rail: rerewhenua - flowing across the land



The design represents the fluid movement of trains across Aotearoa. 'Rere' is to flow or fly. 'Whenua' is the land. The koru forms represent the earth, land and flora that trains pass over and through. The letter 'R' is present, standing for 'Rail'.

Sandy acknowledges Papatūānuku (Earth Mother) and Tāne Mahuta (God of man and forests and everything that dwells within) in the creation of this Kōwhaiwhai.



Transport Accident Investigation Commission

**Recent Maritime Occurrence reports published by
the Transport Accident Investigation Commission
(most recent at top of list)**

MO-2025-201	F/V Antarctic Discovery, Incapacitation of crew, Lyttelton dry dock, Port of Lyttelton, 21 February 2025
MO-2025-203	Bulk carrier, Thor Nitnirund, Serious injury, Cook Strait, New Zealand, 20 March 2025
MO-2024-204	MO-2024-204: Passenger and freight ferry Aratere, grounding, Titoki Bay, Picton, 21 June 2024
MO-2023-201	Passenger vessel, Kaitaki, loss of power, Cook Strait, New Zealand, 28 January 2023
MO-2025-202	Jet boat Discovery 2, allision with canyon wall, Skippers Canyon, near Queenstown, 25 February 2025
MO-2024-207	Pilot vessel, Takitimu II, grounding, Stirling Point, Bluff, New Zealand, 26 December 2024
MO-2023-205	Bulker carrier, Achilles Bulker, loss of rudder, off the Port of Tauranga, 24 July 2023
MO-2024-203	Fishing vessel, Chokyu Maru No.68, grounding, The Noises, Hauraki Gulf, 16 April 2024
MO-2023-203	Container vessel, Shiling, loss of control, Wellington harbour, 15 April 2023
MO-2024-201	Passenger vessel Fiordland Navigator, grounding, Doubtful Sound, 24 January 2024
MO-2022-206	Charter fishing vessel, i-Catcher, capsized, Goose Bay, New Zealand, 10 September 2022
MO-2023-206	Fishing vessel, Austro Carina, Stranding at Red Bay, Banks Peninsula, 24 September 2023
MO-2023-202	Collision between Passenger Ferry, Waitere and recreational vessel, Onepoto, Paihia, Bay of Islands, 13 April 2023
MO-2023-204	Bulk carrier, Poavosa brave, serious injury, off Tauranga, 23 June 2023

Price \$11.00

ISSN 3021-4130 (Print)
ISSN 3021-4149 (Online)